Tally Sheet
RFQ 2354-A: Crosstown HSP 1 Pump & Motor Repair

	Cornerstone Mechanical
Description	Price
High Service Pump #1 Control Valve Replacement, per specification	\$ 87,826.00
Contingency Allowance, shall only be used with prior written approval of the County Administrator	\$ 4,000.00
Total Quote	\$ 91,826.00